



a=Iu b=PHSH stator v-w interchanged error 07LH



	A	B
ATN	1 V	5 V
CPL	DC	DC
OFS	2.04 V	-15.2 V
MTB	10 ms	10 ms
DLY	-1	-1
SMP	512	512
DAT	06/22/94	06/22/94
TIM	15:05:21	15:05:21
ATN		
CPL		
OFS		
MTB		
DLY		
SMP		
DAT		
TIM		

a=Iw b=PHSH stator v-w interchanged error 07LH



	A	B
ATN	1 V	5 V
CPL	DC	DC
OFS	2.04 V	-15.2 V
MTB	10 ms	10 ms
DLY	-1	-1
SMP	512	512
DAT	06/22/94	06/22/94
TIM	15:07:05	15:07:05
ATN		
CPL		
OFS		
MTB		
DLY		
SMP		
DAT		
TIM		

low speed rotor control phase shift check failed, stator lines v=2 w=3 interchanged  
roco-low-phsh-fail.doc